Brookhaven National Laboratory – Photon Sciences - National Synchrotron Light Source						
Beamline Hazard Analysis - Beamline X10B						
LS-BHA-X10B	Revision:	02	Effective: 10/5/11	Page 1 of 1		
The following tasks are included in the beamline safety review. Any operations not listed here, or performed by others than						
those listed, need additional review by ES&H personnel and/or beamline personnel.						

Prepared By:	S. Bennett, L. Fareria	Approved By:	Lori Stiegler

Tasks / Equipment	Performed by:		Controls	
	Beamline	Users		
	Staff			
Inert compressed gas	Y	N	<ul> <li>Compressed gas training – TQ-COMPGAS1 or NSLS User training</li> <li>Transport cylinders using a cylinder cart</li> <li>Properly secure cylinders</li> <li>Wear safety glasses with side shields while connecting lines</li> <li>Leak check gas lines</li> </ul>	
Solvents	Υ	Y	<ul> <li>Limit quantities at beamline to &lt; 250 ml</li> <li>Use PPE - safety glasses, nitrile gloves</li> </ul>	
Ergonomics concerns – moving/lifting	Υ	N	<ul><li>Be aware of body posture,</li><li>Ask for help in moving or lifting</li></ul>	
Ergonomics concerns – pinch points/sharp edges – moving table	Y	N	<ul><li>Administrative control</li><li>Training</li></ul>	
Cutting/razor blades	Y	Y	<ul> <li>Be aware of hand positioning</li> <li>Use safety knife when possible</li> <li>Consider using cut resistant gloves for frequent cutting tasks</li> </ul>	